E OPTICON

[01 Nov 2024]

Dear customer,

This letter is to inform you about the upcoming discontinuation for:

- 13131 PX-20, 15065 PX-20 MSD

We sincerely appreciate your past purchase of this product and do hope that its use has met your requirements. After a thorough review of our existing product offering however, we decided to discontinue this product.

When you look for a replacement, we recommend the following:

- 15123 OPN-6000

Effective date: immediately Last time buy order: N.A.

Opticon will support and service discontinued products as long as the required parts are available.

Please contact your local Opticon representative for any questions or concerns you may have.

Thank you for your understanding and cooperation.

Sincerely,

Opticon Sensors Europe B.V.

Opaallaan 35 - 2132 XV hoofddorp - The Netherlands - +31 (0)23 569 27 00 - sales@opticon.com - Rabobank Hoofddorp (IBAN NL33 RABO 0324 5157 74) acc. no. 32.45.15.774 SWIFT/BIC RABONL2U - ING Bank Hoofddorp (IBAN NL52 INGB 0656 9126 69) acc. no. 65.69.12.669 SWIFT/BIC INGBNL2A Registered Chamber of Commerce Amsterdam no. 34064005 - BTW/VAT no. NL008701325B01 - EORI 008701325